

MMTB CLOCK No.81

The clock mechanism was cleaned and oiled on 10th March 2013. The missing pawl spring on the Left main spring was replaced with a small section of spring steel. The second pawl on the Left main spring was located in the base of the clock cabinet and reinstalled after modification.

The Recording Mechanism was not serviced or reconnected to the clock due to it no longer being in use.

Rolf Jinks