

(054) 420222

Army Survey Regiment
B Box 1004
Bendigo Vic 3550.

Ref No. 985-1-7.

May 1989.

Chief Engineer
Headquarters Third Military District

"FORTUNA VILLA" BENDIGO - PARTIAL GARDEN RESTORATION.

References

- A. Our letter 985-1-7 dated 17 Oct 1988 (original proposal and plans).
- B. Your AW 2830/88 dated 30 Nov 88 and ACS letter dated 28 Nov 88.
- C. Your BMD 560-3-147 (AW 3145/88)

1. Please find attached the further information requested in Ref C. They are:-

- a. a photocopy of detail from Dept of Services Plan 631/005 Sheet 2 BENDIGO "FORTUNA" showing layout now in situ and location of power, water and sewage lines.
- b. a sketch plan of the proposal. It should be reiterated that the only vegetation to be removed will be a poor specimen of Blue Spruce and some Pelargoniums all having being added to the area about mid 1975.
- c. an impression of the aspect after installation.

2. The fountain as pictured was chosen because it was the only one available that came close to the original without going to the expense of having a 'one-off' copy cast. However this committee is willing to attempt to modify and downgrade the fountain to accommodate the taste of the ACS by removing the cherub and replacing it with what looks like two inch water pipe (see Annex A to Ref A)

3. As indicated in the original proposal all costs of materials and installation were to be met by this Committee, who are not prepared to bear any costs of studies reports submissions etc that originate outside of this unit.

J.W. WINZAR.

Lieutenant Colonel

Commanding Officer

Army Survey Regiment.

- Annex
- a. photo copy of engineers plan.
 - b. sketch plan of proposal.
 - c. sketch of proposal on completion.