

Mid Western
2-2-71

Works Supt.

Car Dept Monthly Report. Ending 31-1-71

- 70 Standard brake blocks renewed.
- 10 Pony " " " " " "
- Car No 11 Replaced new lead to motor. No end.
- " " 13 Renewed side frame.
- " " 14 Exhaust repair completed.
- " " 17 Rehubbed.
- " " 26 Rehubbed.
- " " 26 Renewed side frame.
- " " 26 Repairs to damage. RR/41. BAN 4595.
in progress
- " " 39 Rehubbed & truck overhaul.
- " " 41 Renewed compression block & backing 1 end.

S.S. DeLong

Works Supp.

Mid Western

2-2-71

for Depot Monthly report ending 31-1-71

- 70 Standard. brake blocks renewed.
10 Pony " " "
Bram No 11 Replaced new lead to motor. No 1 end.
" " 13 Renewed side frame.
" " 14 Exterior repaint completed.
" " 17 Rewheeled. damage completed.
" " 26 Rewheeled. later under intake coil.
" " 26 Renewed side frame.
" " 36. Repairs to damage. AR/A1. BA2/4595.
" " in progress.
" " 39 Rewheeled & truck overhaul.
" " 41 Renewed. compression block & casting 1 end.

S. S. Lakey.

Works Dept

Chief Clerk

1-3-77

Car Depot Monthly Report. Ending 28-2-77

33 Standard. brake blocks renewed.

72 Pony " " " "

Tram No 11 Renewed earth lead on motor.

" " 12 Rewheeled to equalizing bar No 1 end.

" " 18 Rewheeled. damage completed. H/R 5. BA 214593

" " 28 Repairs to damage completed. H/R 44. BA 214594

" " 30 Renewed insulation under interpole coil.

" " 33 Renewed trolley base.

" " 33 Renewed armature No 1 end.

" " 34 Side frame renewed.

" " 36 Repairs to damage completed. H/R. 41. BA 214595.

" " 37 New leather in brake cylinder.

S B Lakey.

Merid Western

1-4-71

Works Sept.

Car Dept Monthly Report ending 31-3-71

92 Standard brake blocks renewed.

22 Pony " " " "

Tram No 13 Repairs to burnt controller leads

" " 14 Renewed brake equalizing bar No 1 end.

" " 18 Repairs to damage completed RR/51 BA 214593.

" " 18 Renewed roller bearings in trolley base.

" " 27 Renewed lead to motor No 1 end.

" " 30 Rewheeled. brake wheels 1st end

" " 31 Renewed brake shoe holder. leads

" " 34 Renewed lower arm on line breaker.

" " 43 Repairs to brake adjuster. built up

37 Renewed brake rod S.S. No 2 end

43 Repairs to burnt out line breaker leads.

Scrubber bar. Renewed with S.S. Lacey.

37 Renewed controller

S.S. Lacey

Works Supt.

Atid Western

11-5-77

Car Depot Monthly Report. Ending 30-4-77

- 37 Standard brake blocks renewed
22. Pongy " " " " "
Tram No 11 Repairs to burnt out motor leads
17 Replaced S-H brake gear No 2 end.
18 Renewed armature No 2 end.
18 Renewed gear case No 1 end.
21 Renewed valve in compressor head.
32 Renewed air brake valves 1 & 2 ends
33 Renewed two field & one in hole coils
33 Removed & renewed insulation on resistor
33 Truck overhaul. side frames built up.
37 Renewed brake rod to S. No 2 end.
43 Repairs to burnt out line breaker leads.
Scrubber car. Renewed ~~rod~~ panel board
in controller.

S. S. Raper.

S. S. Raper.

Mid Western.

1-6-71

Works Supt.

Car Depot Monthly Report Ending 31-5-71.

- 54 Standard brake blocks renewed.
13 Pony " " " "
Tram No 12. Renewed trolley base.
" " 13 Renewed pilot bracket spring.
" " 17 Renewed spring in compressor switch.
" " 17 Renewed brake cylinder waster & push rod.
" " 26 " & adjusting pull rod.
" " 18 Repairs to burnt out motor cables.
" " 18 Renewed trust bar angle plate support brace.
" " 26 Renewed armature No 1 end.
" " 26 Renewed bottom field coil No 1 end.
" " 26 Renewed circuit breaker switch No 1 end.
" " 26 Renewed pinion on motor No 1 end.
" " 27 Renewed trust rod bracket.
" " 31 Renewed trust rod.
" " 41 Replaced R/F pony wheels 1 & 2 ends

S S Rakey.

Mid Western

1-7-71

Works Suppl

Car Depot Monthly Report ending 30-6-71

- 55 2 Standard brake blocks renewed.
- 13.0 Pony " " " "
- Tram No 11 Truck overhaul side frames built up.
- " 31 1 new body spring post.
- " 34 2 claw valves in compressor head.
- " 36 Repairs to hand brake gear.
- " 36 Renewed pony wheels 1 & 2 ends
- " 37 Rewheeling in progress
- " 39 Renewed pawl in brake adjuster.
- " 40 3 Renewed pony wheels 1 & 2 ends.
- 39 Renewed brake rod 401 end.
- 41 Renewed side frame 402 end 405

SS Lakay.

SS Lakay.

STATE ELECTRICITY COMMISSION OF VICTORIA

Works Supt.

Clive Weston

Date 2-8-71

Car Depot Monthly Report ending 31-7-71

- 62 Standard brake blocks renewed.
 20. Pony " " "
 Tram No 111 Repairs to trigger gate.
 21 Renewed gear case No 1 end.
 27 Replaced brake gear S-H No 1 end.
 33 Renewed trolley base spring
 34 Renewed compression bracket &
 spring post. No 1 end.
 34 Renewed body spring post.
 37 Rewheeled.
 39 Renewed brake rod No 1 end.
 41 Renewed side frame No 2 End K.B.S.

S.S. Lakey.

