

MELBOURNE AND METROPOLITAN TRAMWAYS BOARD.

NOTICE TO INSPECTORS - SOUTHERN SYSTEM.

EXCESSIVE SPEED OF TRAMS AND FAILURE TO
OBSERVE "SLOW DOWN DISCS" & COMPULSORY STOPS
EN ROUTE TO DEPOT ON LAST ROUND AT NIGHT.

Complaints are being received of the excessive speed of trams
and the failure of Drivers to observe "Slow Down Discs" &
Compulsory Stops, when running to depot from the respective
termini, particularly on the last round at night.

Inspectors are requested to give this matter special attention
and report all cases detected for disciplinary action.

Arrange for a check to be taken on each route once a month.

forward check in duplicate to the DIST. T. SUPT, together
with a record, if any, of overtime worked as a result of above.

27/5/52.

J.N.C. HARRY,

DIST. TRAFFIC SUPT., S.S.

Mr. Walker