Training Session

For

Entering, Berthing and run out From Kew depot Maintenance pit

Training – Kew tram Depot.

This document is use in conjunction with practical training therefore any questions please ask your trainer.

Act Senior Depot Trainer Rodney Fernando Date: 08/09/2008

Learning outcomes

At the end of this session

- > Participants should able to enter, berth and run out "A" class and "C" class trams in and out of the maintenance pit safely.
- > Participants must understand Health and Safety issues when berthing and running out from the Kew Depot pit.
- > Participants must able to follow correct safe working procedure
- When they get out of the tram
- When they walking in the pit

Safe working procedures

- > When entering the shed driver's must be aware and follow normal run in procedures such as checking correct road, sounding the GONG, looking for people working etc.
- No "A" class trams on Road Three(3) and Four (4)
- No "C" class trams on Road one (1) and two (2)
- > No checking sand and track brake inside the pit. Drivers must drive out of the pit to check sand and track brake
- > Stop the tram in line with Stop sign beside the rail.
- > Before entering, pull your mirrors in.

- > Drivers must walk between the yellow lines when walking in and walk out of the pit.
- A class trams Drivers must not open the doors

 Drivers must turn off FR, Battery and Pantograph down. Open the flap and raise the door handle inside and manually open the appropriate door then safely walk down the ladder.
- > C class trams Drivers must open the doors in the platform side only
 Metal net is in place against all the doors except door line up with the platform
 therefore carefully alight to the platform then safely walk down the ladder.
 (Make sure all buttons are up before leaving the tram)
- In case of emergency such as tram brake down, live wire come to contact with the tram or platform driver must put the pantograph down, call F.O.C and wait inside the tram until help arrive.
- > It is important take extra care when walking in the pit to prepare the tram or when finishing your work because there may be various equipment on the ground. The drivers must sound the GONE before running out from the pit

End of the shed

