



Mr K. Douglas
Depot Foreman

Ballarat

20-12-60

Repairs to damage tramcar N° 26

Damaged 14-12-60 W.GEN 208

A.R/34 - C.W-GEN.206-3-61

Repairs completed 20-12-60

~~1 Pint Dulux enamel tramway green~~

Labours

Coach builder 1 1/2 hrs

" painter 1 hr

~~Coach Paint~~ Material

10' x 6 1/2" x 3/4" K.D. Hardwood dressed
1/2 Pint Dulux enamel tramway green

D J Erwin

Additional charge

1 hr Coach painter

30/3/61

D J Erwin

Mr K. Douglas
Depot Foreman

Ballarat

27-3-61

Repairs to Damaged tramcar N^o 33

Damaged 25-2-61

A.R. 48 - C.W. GEN 208

Repairs completed 6-3-61

Material

1 Pint Dulux enamel tramway green

Coach Labour 11 hrs

L.H. Fitter Painter 2 hrs

Coach Painter 2 "

D.J. Irwin

D.J. Irwin

Mines

Mr K. Douglas

Ballarat

Depot Foreman

27th April 61

Repairs to damage tramcar N° 13^{10 110}
Damaged 20-4-61 - 6-61 A.R./65
A.R./55 - C.W.GEN 209
Repairs completed 27-4-61

Material

1 Pint Dulux enamel tramway green

Labour

2 Coach builder 11 hrs
" painter 1 "

D J Erwin

D J Erwin

Minors

Mr K. Douglas
Depot Foreman

Ballarat

27-6-61

Repairs to damaged tramcar No 40
Damaged 20-6-61 F.R/65
C.W.GEN.212

Repairs completed 27-6-61

Material

1- 4" x 14" x 1/4" Mirror cut

1 Pint Dupon enamel tramway green

Labour

L.H. Fitter 3 hrs

Coach Builder 12 hrs

Coach Painter 3 hrs

Workshop Fitter

D J Irwin

Minor

Minor

Mr H. Douglas

Ballarat

Depot Foreman

17-7-61

Repairs to damaged tramcar N° 39
Damaged 22-5-61

A.R/62 - C.W.GEN 211

Repairs completed 7-7-61

Material

1 Pint Dulux Undercoat

1 Pint Dulux enamel tramway green

Labour

Coach Builder 12 hrs wood

Coach Painter 3 hrs

Workshop Fitter tramway green

D J Irwin

Minor

D J Irwin

Accountant

Ballarat

Depot Foreman

17-7-61

Repairs to damaged tram N°31

Damaged 6-7-61

A.R./1 C.W.G. EN 213 214

Repairs completed 17-7-61

Labour

Coach builder 2 hrs

Coach Painter 6 hrs

Material

3'3" x 9" x 1 1/4" K. D. Hardwood

2 only Footboard castings

1 Pint Dulux enamel tramway green

1 Pint Dulux enamel tramway green

Minors

D J Jervis

Mr K. Douglas
Depot Foreman

Ballarat

24-9-61

Repairs to damaged tram N°18

Damaged 15-8-61

A. R/H C.W. GEN. 214

Repairs completed 4-9-61

Labour

L. H. Fitter 2 hrs
Coach Builder 6 "
" Coach Painter 1 "

Material

2 Step irons
1 Pint Dulux enamel tramway green

D J Lewis

Minor

Mr K. Douglas
Depot Foreman

Ballarat
27-9-61

Repairs to damage tram N°34

Damaged 15-9-61

17 R/20 - C.W. GEN 215 16

Repairs completed 27-9-61

Material

Labours

3 H. M. Fitter 1 Plus hardwood
Coach Builder 1 Aluminium angle

Labours

Coach builder 4 hrs

D J Irvine

D J Irvine

Minor
9/11/61

Accountant

Ballarat

Depot Foreman

26th Oct 61

Repairs to damaged tramcar N^o 3126

Damaged 17-10-61

A.R/29 - C.W. GEN 216

Repairs completed 26-10-61

Material

Labour

3' 3" x 9" x 1 1/4" K.D. Hardwood

3' 6" x 1" x 1" x 1/16" Aluminium angle

Labour

D.J. Irwin

Coach builder 4 hrs

Minor

D.J. Irwin

Accountant

Ballarat

Depot Foreman

26th Oct 61

Repairs to damage trances No 26
Damaged 20-10-61
A.R/30 C.W.GEN 21817
Repairs completed 26-10-61-10-61
Material

2 Labour
3'3" Coach Builder 2 hrs
36" x 1" x 1" x 1/8" Aluminium angle

D J Irwin

Labour
Coach Builder 4 hrs

Minor

D J Irwin

Accountant

Ballarat

Depot Foreman

26th Oct 61

Repairs to damage frame at No 21

Damaged 21-10-61

A.R./31 - C.W.G.E.N. 217

Repairs completed 26-10-61

Material

Material

2 Step castings

3'3" x 9" x 1 1/4" K.D. Hardwood 5-3-6

3'6" x 1" x 1" x 1/16" Aluminium angle 0

Labour

Coach Builder 4 hrs

Coach Builder 2 hrs

D J Irwin

Minor

D J Irwin

Accountant

Ballarat

Depot Foreman

3-1-8-62

Repairs to damaged Trams No 12

A/R. 7 - B. 220/1/220

Repairs completed 1-8-62

Material

3'3" x 9" x 1 1/4" K.D. Hardwood

2 Step irons
3' x 1" Reflector tape

£ 5-3-6
6-0

Labour

Coach Labour 4 hrs

Coach Builder 7 hrs

D J Servin

Minor

D J Servin

Accountant

Ballarat

Depot Foreman

3-9-62

Repairs to damaged tramcar No 17

A/R. 18 - 2201/222

Repairs completed 3-9-62

Material

3'3" x 9" x 1 1/4" K.D. Hardwood

2. Step irons

Labour

Coach Builder 4 hrs

Coach Builder 3 hrs

D J Ivin

D J Ivin

Munias

9/11/62

~~9/11/62~~

Loach Builders 3 hrs

labor

2 Step iron

3'3"x9"x1 1/4" K.D. Handwood

Material

Repairs completed 3-9-63

APR. 19 - 2201/223

Repairs to damage frames No 12

Deputy Foreman

Ballarat

3-9-62

62

1 end Brake Side 62

N° 12 - 2 end

A/A.45
2201/226

Corner pillars brake side broken
" stanchion damaged
Hand rail brackets = 2 broken
Entrance door damaged
2 Step irons damaged
Bumper bent
Footboard damaged
Side guard board damaged
Tail light crushed
Apron damaged

Accountant
No. 118

FSC 13-160

DEPARTMENTAL

STATE ELECTRICITY COMMISSION OF VICTORIA

TO Depot. Financ. W. Huff.

DATE 1. 6. 66.

Dan

13-18 - No 1 and Brake Side 2

Car hi
Cone
Apr
Hai
Cone
1 S
1
For
S
A
C

Dan,
To avoid delays in collating costs on accident damaged trams the accountant would like us to discontinue the practice of transferring costs of materials used, by means of the Job to Job (These are processed by I.B.M. and it takes a month or more).
In future just attach a note to the completed Workstop Req. listing the material involved and he will make a direct book entry.

Thanks

Bill

Damage tram N° 18 - N° 1 end Brake Side 2
Damaged 4-8-62 10.2 P.M.

Car hit 17" of Bumper bar
Corner pillar broken
Apron damaged
Tail light crushed to be renewed
Corner stanchion bent
1 Step iron bent
1 " " broken
Footboard broken to be renewed
Side guard board " " "
Apron sill split " " "
Entrance door bottom rail & stile
to be renewed
Lighting cowl damaged

Accountant
Depot Foreman

Ballarat

243-9- 62

Repairs to damaged tramcar N°28
Repairs to damaged tramcar N°1010

Accountant
Depot Foreman

Ballarat

2- 9 66

Repairs to accident damage tram car No 39

A/R 12 B.A. 214060

The following material used ^{to} repair damage.

22' x 7" x 2 3/4" Oregon
7' x 3" x 1" K. D. Hardwood
3 Lamp holders @ 1/8
2 Pints Dulux enamel.

Labour.

L. H. Fitter	3 hours
Maintenance Carpenter	4 1/4 hours
Maintenance Painter	5 hours
Shedman	2 1/4 hours.

F. A. Morris

Accountant
Depot Foreman

Ballarat

243-9-

62

Repairs to damage tramcar N°18

A/R. 8 - B. 2201/221

Repairs completed 3-9-62

Material

9'9" x 9" x 1 1/4" K. D. Hardwood

10' x 6 1/2" x 3/4" " " "

6'6" x 2 3/4" x 1 3/4" Dulux tramway green

12' x 3" x 1" " " "

3' x 5" x 1" " " "

2 Step irons

1/2 y. Dulux enamel green

Coach Builder 6 1/2 hrs

" Painter 2 "

L.H. Fitter 2 "

Shed Labour 2 "

Coach Builder 110 hrs

L.H. Fitter 8 hrs

Coach Painter 4 hrs

Fitter (Workshop)

D. H. H. H.

D. H. H. H.

Major

Accountant

Ballarat

Depot Foreman

24-9-62

Repairs to damaged tramcar N° 28

A/R. 23 - C.W. 2201/224

Repairs completed 24-9-62

Material

22 Steps

10' x 6 1/2" x 3/4" K. D. Hardwood

3'3" x 9" x 1 1/4"

1 Pint Enamel Dulux tramway green

Labour

Coach Builders 6 1/2 hrs

" Painter 2 "

L. M. Fitter 2 "

Shedman 2 "

D. J. Irwin
D. J. Irwin

Minors

Accountant

Ballarat

Depot Foreman

324-9-62

Repairs to damaged tramcar N°32

A/R-22 - C.W-2201/225

Repairs completed 24-9-62

Material

26" Stepiroons D. Hardwood

13" Stanchion bracket

10' x 6" x 3/4" " " "
3' x 5" x 1" " " "
6' x 3" " " "

Labour

Coach Builder 8 hrs

" Painter undercoat

L.H. Fitter enamel 3 tramway green

Shed Assistor Tap 2 1/2 "

Labour

Coach Builder 30 hrs

Minor 7 "

D J Gerwin

Minor

Major

D J Gerwin

Accountant

Ballarat

Depot Foreman

31-1-63

Repairs to damaged tramcar No 12

A/R. 45 C.W. GEN 2201/2263

Repairs completed 30-1-63

Material

- 6'6" x 2³/₄" x 1³/₄" K. D. Hardwood
- 3'3" x 9" x 1¹/₄" " "
- 10' x 6¹/₂" x 3³/₄" " "
- 3' x 5" x 1" " "
- 6' x 3" x 1" " "
- 2 Stanchion brackets
- 1 Prismatic headlight lens
- 1 Tail light
- 1 Pint Dulux undercoat
- 1¹/₂" " enamel tramway green
- 5' x 1" Reflector tape

Labour

- Coach Builder 30 hrs
- L. H. Fitter 7 "

Mayor

D J Irvine

Accountant

B Ballarat

Depot Foreman

20-2-63

Repairs to damage tram N° 28
 A/R. 55 - C.W. B 22010/513
 Repairs completed 20-2-63
 Repairs completed 5-3-63

Material

8' x 11 1/2" x 2 3/4" Oregon
 2 Step irons

100' x 6" x 3/8" Baltic 4 flooring

7' x 6 1/2" x 1/2" Oregon

8' x 11" Labour

3 Pieces glass 31" x 26" x 3/16"

Coach Builder 21 hrs

Shedman 11 mel "undercoat white

Shed Assist 6 "tramway green

Labour

D J Stevens

L. H. Fitter 6 hrs

Coach Builder 14 1/2 "

Shedman 23 "

Shed Assist 3 "

Mayor

4 "

D J Stevens

Mayor
2 Trams