0062

20 hrs
tests P100
2/11/23

..... 192

The ORDISH FIREBRICK CO. Pty. Ltd.,
Stud Road, Dandenong

I have this day inspected the Machinery and Tackle, also the Pit, and find same in safe working order.

..... Manager

..... 192

The ORDISH FIREBRICK CO. Pty. Ltd.,
Stud Road, Dandenong

I have this day inspected the Machinery and Tackle, also the Pit, and find same in safe working order.

..... Manager

comp 1 hr
machine, etc 45 mins

..... 192

The ORDISH FIREBRICK CO. Pty. Ltd.,
Stud Road, Dandenong

I have this day inspected the Machinery and Tackle, also the Pit, and find same in safe working order.

..... Manager