

CAR HISTORY

Car No. 939
KW

Class S.W.6 Type BOGIE Date Built 26.2.48 Date into Service 26.2.48

Overhaul 01	Re-Varnish 02	Seats Re-Varnish	TOTAL MILEAGE 01+02	Date	Alterations, Remarks
		4'51.			4 Extra Strap Hangers on Saloon
	1.52	02.61	135604	27.1.48	Accident:- Est repairs £1:5:10
<u>10.59</u>		9.63	286613	21.1.49	" " " " £3:13:4
12/6/03	12/6.03	3-65		27.2.49	" " " " 7/9
	4/63.03			23.6.49	Into W/shops:- No.1 motor defective Change of Trucks & Comp
	3/69.03			19.7.49	Accident:- Est repairs 9/80
<u>4/85.03</u>	<u>8/82</u>			27.7.49	Accident:- Est repairs 38.9.11
				27.7.49	Into W/shops:- Collision repairs New mirror feat.
				26.8.49	" " " " Line breaker connections tested. Leads reverse
				9.11.49	Accident:- Est repairs £1:2:2
				11.11.49	Accident:- Est repairs 3/11
				16.2.50	" " " " 13/11
				16.2.50	" " " " 7/11
				16.7.50	" " " " 16/3
				31.12.50	" " " " 17/11
				26.2.51	" " " " 3/10
				<u>4'51</u>	<u>Windscreen wipers altered from top to side of dash</u>
				9.4.51	Into W/shops:- Mileage Desp 20/51 ^{General Truck} & Compressor
				30.4.51	Accident:- Est repairs 3/10

2

Car 939

9.6.51	Replace strap hangers with bakelite fittings
6.8.51	Accident:- Est repairs £93.
11.9.51	Accident:- Est repairs £2:19:5
14.10.51	Accident:- Est repairs £1:9:7
23.10.51	Into W/shops:- " " " " £1-2-6
31.10.51	Into W/shops:- bracked wheel No.2 gear piece out of head Desp 19/51 Comp. change. No.2 wheels parts chg.
10.51	Destination door holding device fitted.
11.51	Control telephone No. in M/Mans Cabin.
<u>18.11.51</u>	<u>Accident:- Est repairs £54. 11. 9.</u>
12.51	Motorman's cabin bulkheads painted cream.
3.52	Flag sockets fitted to car.
<u>29.3.52</u>	<u>Head lights replaced- canopy lighting removed.</u>
<u>14.3.52</u>	<u>Into W/shops:- collision repairs 02. Desp 28/4/52.</u>
9.5.52	Accident:- Est repairs £1.3.4
13.8.52	" " " " 19/11
3.11.52	Into W/shops:- Low wheels. Desp. 8/12/52. Trucks & Comp. changed.
22.4.53	Accident:- Est repairs 10/9
7.5.53	Into W/shops:- Compressor's passing oil badly Desp 12/5/53 Comp. change
15.12.53	Accident:- Est repairs £1.19.3
12.4.54	" " " " 4/11
14.5.	Into W/shops:- Low wheels. Insp. Mileage. Desp. 26/5. Trucks & Comp. changed.

23-7-54	Accident - Est. repairs	15/9	
8-9-54	" " "	9/9	
30-8-54	" " "	15/9	
8-12-54	" " "	15/9	
5-8-55	" " "	L1-13-3	
2-9-55	" " "	no Damage	
18-9-55	" " "	L5-12-4	
28-11-55	" " "	L1-5-3	
12-12-55	" " "	no Damage	
17-1-56	" " "	6/8	
17-1-56	" " "	L2-1-0	
23-2-56	" " "	L3-5-1	
31-5-56	Fitted for side Panel of doors		
21-7-56	Accident - Est. Repairs	L2-9-7	
9-8-56	" " "	14/8	
23-8-56	" " "	4/2	
29-8-56	Into w/shops - Comp. pumping oil. Examine door engine pipes for oil.		Dep. 6/9/56. T.C. chgd.

6/55 Transferred OP
for Boule & service.

7-9-56	Accident Est. Repair	5/2	
14-9-56	" " "	5/2	
30-7-56	Fitted for Apron Panel Adverts.		
18-12-56	Acc 1. Est. refs.	L2-5-6	
17-1-57	" " "	L4-8-3	
25-3-57	" " "	L1-7-2	
3-4-57	" " "	5/3	
10-4-57	" " "	5/3	
17-4-57	" " "	5/3	
17-7-57	" " "	9/6	
22-8-57	" " "	5/3	
30-8-57	" " "	5/3	
26-9-57	Into w/shops: Compressor. Dep. 26/9/57 Comp. changed.		
24-10-57	Acc. Est. refs.	5/3	
18-11-57	" " "	L9-0-0	
12-11-57	No Damage.		
24-1-58	" " "		
5-5-58	Acc. Est. refs.	5/3	

5. 6. 55	Acc Est rep. £2. 10. 9
14. 6. 55	Into w/shops
4. 6. 58	Acc Est rep 9/6
2. 9. 58	INTO W/SHOPS - FOR INSPECTION OF PAINT WORK DESP 2. 9. 58
13. 9. 58	ACC: EST REPS £2. 10. 9.
23. 9. 58	REGLAZE W/SHIELDS + M/M DOORS 3/16" A.P GLASS.
24. 9. 58	INTO W/SHOPS - GLAZING. DESP 26/9/58.
16. 10. 58	Acc Est rep 14/11
16. 10. 58	" " " 5/3
30. 10. 58	" " " £1. 11. 6.
4. 2. 59	" " " 4/3
15. 6. 59	" " " £2. 6. 6
3. 8. 59	Into W/S: Glaz Mat 102 Water Desp 19/10/59 01
8. 59	Lightning brackets altered
9. 59	Shops fitted on above bond Brackets + Drainage + lightning sheet.
10. 59	Spolight Shields for Resistance Boxes
16. 11. 59	Acc. Est rep 12/3
4. 2. 60	" " " 12/3

9/59
net to Kew

28. 3. 60	Acc. Est rep. 4/8
31. 5. 60	" " " MAT. 1/- LAB. 1/2 HR
3. 6. 60	" " " 3/3 " 1 "
20. 6. 60	Into W/shops: Glaz Mat 102 Water Desp 20/6/60
16. 9. 60	Acc. Est rep. MAT. 1/- LAB. 1. HR
27. 9. 60	" " " £1. 3. 0 - 1 "
28. 11. 60	" " " £2. 0. 0 - 17 : PO 24429
10. 12. 60	" " " £1. 0. 1/2.
6. 2. 61	" " " 1/- 1/2.
29. 11. 61	Into w/shops: - Exchange of Panels Desp 19/12/61 Trucks
30. 8. 61	" " " - Truck exchange Desp 21/9/63 Trucks + beny
17. 1. 62	" " " - Ball Rep Desp 9/6/62
17. 4. 62	Acc Est rep MAT. £12. 4. 0 LAB 13 1/2 HRS PO 25454 11:00
30. 11. 65	Into w/shops: - W/M MAT on Desp 2/2/66 Trucks
12. 8. 66	Acc Est rep MAT. \$33. 07 LAB. 9. HRS
3. 10. 66	" " " \$ 2. 74 " 4 "
16. 12. 66	Into w/shops: Truck Insul Desp 19/12/66

1

Car 939

- 13-5-83: Into workshops for: #2 Motor Disp 24/5/83 #2 Motor chgd.
- 5-2-85: Roof repairs. Disp. 2/4/85.
- 6-5-85: #3 & 4 Motor Pinion. + #3 Axle Disp 11/6/85.
- 5-7-85: #1 Motor (Elect). Disp 16/7/85.
- 15-7-86: #3 Motor Elect. Disp 25-7-86.
- 11-8-87: S/m to W/S Trucks Low Wheels.
- 25-8-87. T-T-X-907. W/Shop to Sturteeb.
- 24-9-88 STA/M to W/S No. 2 + 4 MOTOR ELECT.
- 18-10-88: WS TO SM # 3 & # 4 MOTORS CHANGED 18-8-89 SM TO WS TROLLEY BASE, LIGHTING, TROUINGING & MOTOR LEAD 28-8-89 WS TO SM TROLLEY BASE, LIFE GUARD, TROUINGING & MOTOR LEAD REPAIR
- 27-11-89 SM TO WS # 4 AXLE SENT 1-12-89 WS TO SM # 3 Motor + # 4 AXLE (WHEELS CHANGED)
- 1-5-90 SM TO WS Compression E. 2-5-90 WS TO SM 27-6-90 SM TO WS COMPRESSOR W. RING & FLUR
- 16-7-90 WS TO SM 31-7-90 SM TO WS # 2 Motor E. 3-8-90 WS TO SM 2-10-90 SM TO WS COLLISION REP.
- 30-11-90 WS TO SM 7-12-90 SM TO WS DETAILMENT REPAIR 12-12-90 WS TO SM
- 18-12-90 SM TO WS # 4 Motor E. 18-12-90 WS TO SM 30-4-91 SM TO WS # 1 + 2 Motor 2-5-91 WS TO SM
- 16-3-92 SM TO WS # 4 Motor E. # 2 P. 6-4-92 WS TO SM T.O. H-X 734 20-7-92 SM TO WS TROLLEY BASE
- 21-8-92 WS TO SM FIRE GUARDS ROOFING 22-4-93 s/m TO W/S No 4 MOTOR ELECT 4-5-93 W/S TO S/M No 4 MOTOR ELECT.

18/

939

- 19-10-93 s/m TO W/S Request by Tram Fleet For inspection. ROSY
- 22-10-93 W/S TO S/M. 26-4-94 s/m TO W/S No 2 + 4 Pinion 4-5-94 W/S TO S/M cm